FAA Airworthiness Directive Compliance Record

2729 East Milham Ave Portage, MI 49002 (269) 381-0790

| Content Revision: 3/11/ | Ai | Aircraft Registration: | | | | |
|---------------------------------|--|--------------------------|--|------------------------|--------------------------|---|
| FAA AD Number Effective Date | Description | Complied Date Time | Amendment Number Method of Compliance/Applicability | Once or Recur | Next Due Date Time | 1. Facility 3. Cert. Nun 2. Cert. Type 4. Author. B |
| Manufacturer | Category | Model | | NAME OF TAXABLE PARTY. | | * |
| Cessna Aircraft Compar | ny Airframe | 170B | | Part #: Serial #: | | |
| 48-43-02 12/31/1948 ©ATP | TO PRECLUDE THE POSSIBILITY OF SUCH FAILURES, PISTON PIN & PLUG ASSYS, P/N 25262-A1 (WITH LOOSE FIT PLUGS), CONTD. | | NA | Recur | | 1. Kalamazoo Aircraft, Inc. 2. Repair Station 3. K9AR289N 4. Ralph Michalka |
| 69-15-03 | TO DETECT CRACKS IN THE | | | ©ATP | Signature: | |
| 8/20/1969 | MUFFLER ASSEMBLY | | MA | Recur | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka |
| ©ATP | ©ATP | Marie Barrier | | CATP | Signature: | |
| 73-17-01 8/16/1973 | TO ADVISE THE PILOT CONCERNING PROPER FUEL TRANSFER PUMP OPERATION | | PLW | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka |
| ©ATP | ©ATP | | | ©ATP | Signature: | |
| 74-06-02 3/18/1974 | TO PREVENT POSSIBLE LEAKAGE OF CARBON MONOXIDE INTO THE CABIN HEATER SYSTEM | • | MA | Recur | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka |
| ©ATP | ©ATP | | | ©ATP | Signature: | |
| 78-26-09 1/1/1978 | Superseded by 79-10-14 | | quel copo | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka |
| ©ATP | ©ATP | | | | Signature: | |
| 79-08-03 C 6/6/1979 | TO PREVENT ELECTRICAL SYSTEM FAILURE, SMOKE IN THE COCKPIT, AND/OR FIRE IN THE WIRE BUNDLE BEHIND THE INSTRUMENT PANEL | | PCL | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka |
| ©ATP | ©ATP | | The same of the sa | ©ATP | Signature: | |
| | ©ATP | 0. | ted 3/9/2009 6:44:28AM | | Descri | 1 of 5 |

FAA Airworthiness Directive Compliance Record

2729 East Milham Ave Portage, MI 49002 (269) 381-0790

| Content Revision: 3/11/2009 File ID: *NEW* | | | | | Aircraft Registration: | | |
|--|--|--------------------------|---|---------------------|--------------------------|---|--|
| FAA AD Number Effective Date | Description | Complied Date Time | Amendment Number Method of Compliance/Applicability | Once or Recur | Next Due Date Time | 1. Facility 3. Cert. Nun 2. Cert. Type 4. Author. B | |
| Manufacturer Category | | Model | Part #: | | | | |
| Cessna Aircraft Compan | y Airframe | 170B | | Serial #: | | | |
| 79-10-14 R1 5/30/1988 | TO PROVIDE AN ALTERNATE SOURCE OF FUEL TANK VENTING IN CASE OF FUEL TANK VENT OBSTRUCTION BY FOREIGN MATERIAL, CONTD. | | POW Ventep CAPS INSTALLED | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | A section | | @ATP | Signature: | | |
| 82-07-02 4/8/1982 | TO REDUCE THE POSSIBILITY OF RAPID LOSS OF ENGINE OIL CAUSED BY ICE OBSTRUCTION OF THE ENGINE CRANKCASE BREATHER | ~ 0 | PCW Holed drilled | Once | | 1.Kalamazoo Aircraft, Inc. 2.Repair Station 3.K9AR289N 4.Ralph Michalka | |
| ©ATP | ©ATP | | | ©ATP | Signature: | | |
| 86-26-04 1/6/1987 | Superseded by 2004-19-01 | | | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | ©ATP | Signature: | | |
| 87-20-03 R2 9/24/1990 | TO ASSURE PROPER ENGAGEMENT OF THE SEAT LOCKING MECHANISM AND TO PRECLUDE INADVERTENT SEAT SLIPPAGE | | | Recur | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | ©ATP | Signature: | A STATE OF THE REAL PROPERTY. | |
| 96-12-22 7/31/1996 | TO PREVENT LOSS OF ENGINE OIL CAUSED BY LOOSE OR SEPARATED OIL FILTER ADAPTERS, WHICH COULD RESULT IN ENGINE, CONTD. | | N/A | Recur | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | ©ATP | Signature: | | |
| 99-27-02 1/21/2000 | Fuel selector valve cams or fuel selector valves, when installed, could result in an inadequate supply of,contd. | | N/A NOT CHANGE | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | ©ATP | Signature: | | |
| | CONTROL OF THE PARTY OF THE PAR | | nted 3/9/2009 6:44:28AM | | | e 2 of 5 | |

| 2729 East Milham Ave Portage, MI 49002 (269) 381-0790 | | | Report Produced By: Kalamazoo Aircra Inc. | | | | |
|---|---|--------------------------|--|---------------------|--------------------------|---|--|
| Content Revision: 3/11 | /2009 File ID: *NE | W* | Aircraft Registration: | | | | |
| FAA AD Number Effective Date | Description | Complied Date Time | Amendment Number Method of Compliance/Applicability | Once or Recur | Next Due Date Time | 1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By | |
| Manufacturer Category Mode Cessna Aircraft Company Airframe 170B | | | lodel Part #: | | | | |
| 2004-19-01 C 11/1/2004 | To prevent slippage of the pilot/co-pilot shoulder harness, which could result in failure of the shoulder,contd. | | NA | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | ©ATP | Signature: | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| 100 | | | | | | | |
| The same of | | | THE STATE OF THE S | | | | |
| 1000 | | | | | | | |
| *************************************** | | | | | | | |
| 200 | | | | | | | |
| 14.00 | | | | | | | |
| | | | | | | | |

Printed 3/9/2009 6:44:28AM


©ATP

Page 3 of 5

FAA Airworthiness Directive Compliance Record

2729 East Milham Ave Portage, MI 49002 (269) 381-0790

| FAA AD Number Effective Date | Description | Complied Date Time | Amendment Number Method of Compliance/Applicability | Once or Recur | Next Due Date Time | 1. Facility 3. Cert. Nun 2. Cert. Type 4. Author. B | |
|--------------------------------------|---|--|---|---------------------|--------------------------|---|--|
| Manufacturer Teledyne Continental | Category Engine | Model O-300-A | | | Part #: Serial #: | | |
| 93-10-02 8/12/1993 | TO PREVENT AN ENGINE FAILURE DUE TO A MISSING CYLINDER VALVE RETAINER KEY | | 1800 | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | and the second | | @ATP | Signature: | | |
| 93-11-03 7/13/1993 | TO PREVENT ENGINE FAILURE FROM AN INCORRECT CONNECTING ROD | | V/A | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | 1000 | | ©ATP | Signature: | | |
| 94-05-05 R1 2/13/1996 | TO PREVENT ENGINE POWER LOSS AND ENGINE FAILURE | | PCW AT OLH 641 OLH 8/17/ 98 | Recur | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | 100000 | | @ATP | Signature: | | |
| 98-17-11 C 10/19/1998 | TO PREVENT CRANKSHAFT FAILURE DUE TO CRACKING, WHICH COULD RESULT IN AN INFLIGHT ENGINE FAILURE AND POSSIBLE, CONTD. | | M/A CRAME NOT REPAIR BY NEISON | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | person | ©ATP | Signature: | | |
| 2000-11-51 E 6/7/2000 | Superseded by 2002-13-04 | | | Once | | 1. Kalamazoo Aircraft, Inc. 2. Repair Station 3. K9AR289N 4. Ralph Michalka | |
| ©ATP | ©ATP | 1 | | | Signature: | | |
| 2002-13-04 C 7/12/2002 | To prevent engine failure and loss of control of the airplane due to migration of the magneto impulse,contd. | | MA | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | The state of the s | NV MARKET TO A STREET OF THE PARKET. | SATP | Signature: | | |



2729 East Milham Ave Portage, MI 49002 (269) 381-0790

| Content Revision: 3/11/2 | Ai | Aircraft Registration: | | | | | |
|---------------------------------|--|--------------------------|---|---------------------|--------------------------|---|--|
| FAA AD Number Effective Date | Description | Complied Date Time | Amendment Number Method of Compliance/Applicability | Once or Recur | Next Due Date Time | 1. Facility 3. Cert. Num 2. Cert. Type 4. Author. By | |
| Manufacturer | Category | Model | | | Part #: | | |
| Marvel-Schebler | Appliance | MA-3A | | | Serial #: | | |
| 69-24-03 11/29/1969 | TO PREVENT POSSIBLE POWER LOSSES DUE TO BLOCKAGE OF CARBURETOR METERING PASSAGES BY THREAD LUBRICANT, CONTD. | | MA | Once | | 1. Kalamazoo Aircraft, Inc. 2. Repair Station 3. K9AR289N 4. Ralph Michalka | |
| ©ATP | ©ATP | | 43 | ©ATP | Signature: | | |
| 72-06-05 R2 7/3/1986 | TO PREVENT LOOSENESS OR SEPARATION OF THE THROTTLE ARM | | Pow | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | 100 | | ©ATP | Signature: | | |
| 92-15-16 L 10/5/1992 | Superseded by 93-19-04 | | | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | CATP | Signature: | | |
| 93-18-03 10/29/1993 | Superseded by 98-01-06 | | | Recur | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | | | GATP | Signature: | | |
| 93-19-04 C 10/18/1993 | TO PREVENT A DISRUPTION OF FUEL FLOW TO THE ENGINE, RESULTING IN ENGINE POWER LOSS, ENGINE FAILURE, CONTD. | | Not cHanged | Once | | Kalamazoo Aircraft, Inc. Repair Station K9AR289N Ralph Michalka | |
| ©ATP | ©ATP | HULL BOOK OF | | ©ATP | Signature: | | |
| 98-01-06 2/13/1998 | TO PREVENT DISRUPTION OF FUEL FLOW TO THE ENGINE RESULTING IN FAILURE TO ATTAIN RATED POWER, POWER LOSS IN, CONTD. | | pau pare | Recur | | 1. Kalamazoo Aircraft, Inc. 2. Repair Station 3. K9AR289N 4. Ralph Michalka | |
| ©ATP | GATP | | | SATP | Signature: | | |