			Data Q2/13/2010
			in accordance with a ANDUN TNOTECT
			taspection and found it in airworthy condition.  Tach reading 2540 Aircraft total time  2540 K Engine time 775
		7	107 Ex Engine time 648
2013	722	Z619	Performed Unnual Inspection per FAF 43 KPX D
/12			Inspected hub and Blude no defec noted
			checked tracking and inspected spinner and
			Symmer bulkhead. All applicable AD complied without this time.
			I certify that this Propeller has been insper
			in accordance with an Annual inspection and a
1			Determined to be in Airworthy conditions Page Page

ate **ELITE AIR SERVICE** FAX 517 279-2363 143 E CHICAGO RD COLDWATER MI 49036 PH: 517 278-6516 07/03/2014 N3420M Tach: 2727.54 Installed propeller to engine; torqued all bolts to 65flb; safety wired all bolts; installed spinner. Performed run up ops check and leak checked; no defects noted. I certify that the above component is approved for return to service. Walter H Paegel IV AP3737207 THE PERSON NOT THE PERSON NAMED IN



S/N DY5658B TSN:836.66 Tach: 2728.66 N3420M 7/07/2014 Inspected Propeller per FAR 43 apx D Annual inspection. 1) Inspected attaching hardware and greased hub. 2) Inspected blade tracking, dressed and painted blades. Researched AD's see AD notes for details. Monico Lopez AP3692583IA I certify that this Propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. MONICO LOPEZ AP36925831A Elite Air Service 300 Airport dr Coldwater MI 49036 517 278-6516

Pag



Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

1/2/2017, N3420M, 1977 Piper PA32RT-300 Lance, S# 32R-7885007, Lycoming IO-540-K1G5D, Hartzell HC3YR1RF S#DY5658B, Tach 2837.1, TTP 945.1

Inspected propeller as required by FAR 91.409(a)(1) per propeller checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Filed nicks and painted face. No active AD's found.

All work done in accordance with Piper PA32RT-300 and Hartzell maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This propeller was inspected in accordance with an annual inspection and has been determined to be in an airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA



Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

March 20th 2018, N3420M, 1977 Piper PA32RT-300 Lance, S# 32R-7885007, Lycoming IO-540-K1G5D, Hartzell HC3YR1RF S#DY5658B, Tach 2854.2, TTP 962.2

Inspected propeller as required by FAR 91.409(a)(1) per propeller checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Filed nicks and painted face. No active AD's found.

All work done in accordance with Piper PA32RT-300 and Hartzell maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This propeller was inspected in accordance with an annual inspection and has been determined to be in an airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA







