
DESCRIPTION OF ALL OPERATIONS PERTAINING TO AIRWORTHINESS DIRECTIVES. SERVICE BULLETINS, SERVICE LETTERS, & MINOR ADJUSTMENTS.







93.1

PH: 517 278-6516

300 AIRPORT RD COLDWATER MI 49036

10/01/2015	N727AV	S/N N168827	HOBBS: 151.9	TSPO
Dorfo	ormed Annual insp plied with AD 81-1	ection per FAR 43 apx D at 3-06 propeller blade failure ops checked all test satisfa	nd 91.409(a)(1)	

Hillard D. Hiner Jr. AP3135719IA

I certify that this Propeller has been inspected in accordance with an Annual Inspection and determined to be in Airworthy condition at this time.

Hillard D. Hiner Jr.31357/9IA



Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

July 1st 2016, N727AV Beechcraft G18S S#BA560, P&W R985-39A, Hobbs: 161.2, TT unk TSO 103.2

Inspected RIGHT propeller as required by FAR91.409(a)(1) per checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Filed nick and pointed force nick and painted face.

AD 81-13-06R2 Propeller blade inspection PCW, next due 2020

All work done IAW Beechcraft G18S and Hamilton Standard maintenance documents. Preformed post inspection operational check per FAR43.15(c)(2). This propeller was inspected accordance with an annual inspection and has been determined to be in airworthy condition at this



Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

August 1st 2017, N727AV Beechcraft G18S S#BA560, P&W R985-39A, Hobbs: 202.1, TT UNK, TSO 144.1

Inspected LEFT propeller as required by FAR91.409(a)(1) per checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Filed nick and painted face.

AD 81-13-06R2 Propeller blade inspection PCW, next due 2020

All work done IAW Beechcraft G18S and Hamilton Standard maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This propeller was inspected in accordance with an annual inspection and has been determined to be in airworthy condition at this Rueben A Walkup A&P 3368961 IA time.





Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

September 28th 2017, N727AV Beechcraft G18S S#BA560, P&W R985-39A, Hamilton Standard 22D30-359, S# N186627, Hobbs: 253.9, TT/ TSO 195.9

Established TT on above propeller in accordance with AC 43.9C paragraph g (1)(b). AD 81-13-06R2 Propeller blade inspection is next due 2020. This time correction does not affect the next time of inspection. There are currently no known life limit parts installed on this assembly. Total time on this propeller, hence fourth will be the same as time since overhaul dated 4/16/2010 completed by H&S Propeller Shop

Rueben A Walkup A&P 3368961 IA

Due:	Overhaul			-	
		Mech. Cert. # or Repair Station #			
Year:	Total Time in Service	Description	Description	entit luter	Total Control
Date:					102(6)
Next Inspection Due:	Time Since Overhaul			ASSESS ARREST	northwest tree
		Mech. Cert. # or Repair Station #			

nay



Elite Air Service 300 Airport Dr. Coldwater MI 49036 (517)278-6516

February 23rd 2018, N727AV Beechcraft G18S S#BA560, P&W R985-39A Hamilton Standard 22D30-359 S#N186627, Hobbs 254.7, TT/TSOH 197.6

Inspected LEFT propeller as required by FAR91.409(a)(1)&(b) per checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Filed nick and painted face.

AD 81-13-06R2 Propeller blade inspection PCW, next due 2020

All work done IAW Beechcraft G18S and Hamilton Standard maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This propeller was inspected in accordance with an annual/100 hr inspection and has been determined to be in airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA

Year:	in Service	Docomption		
Date:				
Next Inspection Due:	Time Since Overhaul		to control the set of the set	
		Mech. Cert. # or Repair Station # _		

		HUB & BLADE INSPECTIONS, RE	PAIRS AND ALTERATIONS
Inspected pr Blades, oiled been inspec	opeller IAW I blades. All a ted IAW an 3	FAR 43 Appendix "D" check list, and Ham-Std maintenance AD,s through 5/30/19 complied with and listed. I certify that 100hr/Annual and was determined to be in an airworthy conditional contraction.	manual. Dressed
Joel E. New	ton 5743062	216A&P Joela.Mt	
Year:	Total Time in Service	Description	SOUTH SEAST
Date:			The state of the s
Next Inspection Due:	Time Since Overhaul		19/9/3
	Overnaui		

Mech. Cert. # or Repair Station #.