DATE

19\_







١			AND DESCRIPTION OF THE PERSON	The last of the la	
	PH: 517 278-6516	300	ELITE AIR SERV		
	10/01/2015	N727AV	S/N BA560	HOBBS: 151.9	AFTT: 15352
	1) Performed	Annual inspe	ection per FAR 43 apx	D and FAR 91.406(a)(1)	
				1.207 1 thru 4 no defect neeft and right fuel strainers	
-	4) Lubed ma	in and tail lan	ding gear performed 3	gear swings and 1 emerg	gence swing no defects noted.
			rrosion X all cables at prrode screws as requ		point's pulleys and bellcranks.
	7) Inspected	brake system	and serviced fluid wi	th 5606.	
			ry, serviced fluid level 9-07 control column as	s and charged reinstalled	no defects noted.
_	10) Complied	with AD 75-27	7-09R2 wing structure		
	11) Complied	with AD 78-10	0-01 lower torque tube	no defects noted at this tatisfactory at this time.	ime.
	Les Xan J. A. Alex	11	ops checked an test of		
-	Hillard D. Hiner Jr	AP3135719IA			
	I certify that this A	irframe has b	een inspected in acco	ordance with an Annual In-	spection and determined to be in
	Airwofthy condition	n at this time.			

Hillard D. Hiner Jr AP3/35719IA

© ASA 1993

1	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
<i></i>	16 Ho	HREE RIVERS, MI	and inspected as per 91.411 IAW Pa Appendix E, paragraph A.  CONRAD AERO  CONRAD AE	I certify that the ATC Transponder(s) were tested and inspected as per 91 413 IAW Part 43 Appendix parts and inspected as per 91 411 IAW Part 43 Appendix parts and inspected as per 91 411 IAW Part 43 Appendix parts and inspected as per 91 411 IAW Part 43 Appendix parts and inspected as per 91 411 IAW Part 43 Appendix parts and inspected as per 91 411 IAW BER CONR680.  Signature The altimeter(s) were tested inspected as per 91 411 IAW Bart 43. Appendix parts and inspected as per 91 411 IAW Bart 43. Appendix parts and inspected as per 91 411 IAW Bart 43. Appendix parts and inspected as per 91 411 IAW Bart 43. Appendix parts and inspected as per 91 411 IAW Bart 43. Appendix parts and paragraph B, by 111 IAW Bart 43. Appendix parts and paragraph B, by 111 IAW Bart 43. Appendix parts and paragraph B, by 111 IAW Bart 43. Appendix parts and paragraph B, by 111 IAW Bart 43. Appendix parts and paragraph B, by 111 IAW Bart 43. Appendix parts and parts
		162	,53	© ASA 1993

RECORDING TACH TIME

TODAY'S FLIGHT

TOTAL TIME IN SERVICE **Description of Inspections, Tests, Repairs and Alterations** 

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)



Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

July 1st 2016, N727AV Beechcraft G18S S#BA560, P&W R985, Hobbs: 161.2, TT 15361.3

Inspected airframe as required by FAR91.409(a)(1) per airframe checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Inspected ELT as required by FAR 91.207(d). Next ELT battery replacement is due 8-2018. IFR certs completed next due 7-2018, Removed and replaced the avionics master switch with a new MS35058-22, ELT battery with new BP1005, blead brakes, serviced left M strut with nitrogen.

AD 75-27-09R2 Wing spar inspection not due until 16060 hrs or in 698 hrs

CW AD 77-19-07 Control Column Cracking, CW by inspection next due in 300 hrs or at annual

All work done IAW Beechcraft G18S maintaince documents. Preformed post inspection operational check per FAR43.15(c)(2). This airfir was inspected in accordance with an annual inspection and has been determined to be in airworthy condition at this time

© ASA 1993

Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TODAY'S TOTAL RECORDING TIME IN FLIGHT TACH Facility. (See back pages for other specific entries.) SERVICE TIME ELITE AIR SERVICE FAX 517 279-2363 143 E CHICAGO RD COLDWATER MI 49036 PH: 517 278-6516 S/N: BA-560 **Beechcraft G18S** Hobbs: 170.0 N727AV 08/15/2016 Removed both G-35 batteries S/N: G02732228 and G02732242. Replaced both with new G-35 batteries S/N: G02925837 and G02925826. Performed ops check; check satisfactory at this time. Walter H Paegel IV AP3737207 IA. © ASA 1993







∌pair

**ELITE AIR SERVICE** 

PH: 517 278-6516 143 E CHICAGO RD COLDWATER MI 49036 FAX 517 279-2363

02/06/2017

N727AV

Beechcraft G18S

S/N: BA-560

**Engine: R985-14B** 

Hobbs: 0174.71

Removed right engine gauge P/N: 22-803-09 S/N: G104 out for REPAIR to MAI and reinstalled. ALL work performed using G18S maintenance documents. Performed a run-up ops and leak check; no defects noted at this time.

Marse A Bely 1 W Walter H Paegel IV AP3737207

ASA 1993		

19

DATE 19



PH: 517 278-6516

143 E CHICAGO RD COLDWATER MI 49036

FAX 517 279-2363

07/27/2017 N727AV

Beechcraft G18S

S/N: BA-560

Engine: R985-14B

Hobbs: 202.1

Removed and replaced both main tires with new P/N: AA485 and new tubes P/N: GL-1113. Installed new tailwheel tire P/N: AD2Y6 and new tube P/N: TR-20. Removed pilot and co-pilot seats removed all existing sheepskin hides and installed new sheepskin hides P/N: CSC016 from Skandia. All materials used comply with FAR 25.853(a)(1)(ii) burn certification. Removed and replaced tailwheel locking pin with new P/N: 404-188683. Performed a run-up ops and leak check; no defects noted at this time.

Walter H Paegel IV AP3737207

© ASA



Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

August 1st 2017, N727AV Beechcraft G18S S#BA560, P&W R985, Hobbs: 202.1, TT 15401.9

Inspected airframe as required by FAR91.409(a)(1) per airframe checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Inspected ELT as required by FAR 91.207(d). Next ELT battery replacement is due 8-2018. IFR certs next due 7-2018,

AD 75-27-09R2 Wing spar inspection not due until 16060 hrs or in 657.9 hrs CW AD 77-19-07 Control Column Cracking, CW by inspection next due in 300 hrs or at annual

All work done IAW Beechcraft G18S maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This airframe was inspected in accordance with an annual inspection and has been determined to be in an airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA

		1
SA 1993		

			A STATE OF THE PARTY OF THE PAR	
DATE 19	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations  Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair  Facility. (See back pages for other specific entries.)
04/03	18 4	tobbs	254	See wot 7006 for details of inspection
04-06	10			VFR only
				Sign Sign
				that the same of t
				STUDY TO THE AND THE A
				TOUR DESTRUCTION OF THE PROPERTY OF THE PROPER
				POR SER PROPERTY OF THE PROPER
				A SO
-				R C9N
				A A A A A A A A A A A A A A A A A A A
_				So
				© ASA 1993



Elite Air Service 300 Airport Dr. Coldwater MI 49036 (517)278-6516

February 23<sup>rd</sup> 2018, N727AV Beechcraft G18S S#BA560, P&W R985, Hobbs: 254.7, TT 15453.7

Inspected airframe as required by FAR91.409 (a)(1)&(b) per airframe checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. Inspected ELT as required by FAR 91.207(d). Next ELT battery replacement is due 8-2018. IFR certification next due 7-2018. Removed and replaced following items: Display lens on KX155 with used serviceable unit. Left fuel selector seals TX90926-2, TC15261, TC15106-1 and TC15143. Vacuum system relief filters RAB3-5-1. Repaired cargo door jamb that was damaged, by replacing damaged material. Replaced small section of damaged skin under left side of the horizontal stabilizer, from the root outboard to the first rib, primed and painted area after sheet metal repair. Labeled circuit breakers as needed. Welded small crack on right exhaust overboard pipe.

AD 75-27-09R2 Wing spar inspection not due until 16060 hrs or in 607.8 hrs CW AD 77-19-07 Control Column Cracking, CW by inspection next due in 300 hrs or at annual

All work done IAW Beechcraft G18S maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This airframe was inspected in accordance with an annual/100hr inspection and has been determined to be in an airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA

ATE TOTAL	Reference	e of Major Repairs an	nd Major Altera	tions To		
05/31/2019	N727AV 196	E A I F 50 BEECH G18S	RSE	ERV	CE	
Inspected Aircraft Maintenance	ft IAW an ANN anual. Greased boost pump re Right hand bra Battery due AP AD complied van Annual insp	NUAL inspection per F d and lubed all hinge eplaced with serviceal ake caliper new seals PRIL 2021. Jacked aircr with and listed through ection and was detern	FAR 43 Appendition points, cables, judicing points, part points, part gear retract points, part gear retract points, part gear retract points, part gear retract points, part part points, part part points, part part points, part part part points, part part part part part part part part	HOBBS: 286  x "D" check list a ack screws and control of the contr	.2 TTAF: 15485 and Beech G18S hains. Right hand w AN fittings and "INOP" ELT checked mergency	5.2
Joel E. Newton	574306216 IA	Joels, motor	8			_
					64	ASA 1993

TAL ME IN ERVICE	Reference of Major Repairs and Major Alterations To  FAA Form ACA-337 by Date, or to the Work Order by Number and the Approving Agency
	Premier Avionics CRS#: 7PMR634B 4424 Altitude Drive., Ft. Wayne, IN 46809  N: