

3AF32C87-NIR/S82NC-5.5

S/N:788984



The Standard

PROPELLER LOG

ASA-SP-L

SERVICED BY

BANIAN
PROPELLER
SERVICE

OVERHAUL • SERVICE
REPAIR

FAA CERT. REPAIR
STATION B2PR308J

FT. LAUDERDALE EXECUTIVE AIRPORT 1-800-200-2031

Propeller Record General Information

Propeller Manufacturer McCawley

Model 3AF32C87-NFR

Type 3blade full feathering

Hub Series # 788984

Blade # S-82NC-S.5

Date of Manufacture _____

F47444YS

F48033YS

F48134YS





1575 W. Commercial Blvd.
Fort Lauderdale, FL 33309
(954) 491-3170 Fax (954) 491-2006
FAA Certified Repair Station No. B2PR308J

Make/Model

Serial #

Aircraft Installed On: _____

1. United States of America		2. FAA FORM 8130-3 AIRWORTHINESS APPROVAL TAG U.S. Department of Transportation Federal Aviation Administration			3. System Tracking Ref. No. 72177	
4. Organization 		1575 W. Commercial Blvd. Fort Lauderdale, FL 33309 (954) 491-3170 Fax (954) 491-2006 FAA Certified Repair Station No. B2PR308J			5. Work order, Contract, or Invoice Number: 72177	
6. Item	7. Description	8. Part Number	9. Elig.	10. Qty.	11. Serial/Batch Number	12. Status/Work
1	McCauley Aircraft Propeller	3AF32C87-NIR/582NC-5.5	*	1	788984	NEWLY OVERHAULED
13. Remarks <u>overhauled propeller per McCauley manual 710930 and 830415. A.D. notes checked through bi-weekly issue 98-18.</u>						
Details on file at this Repair Station under work order referenced in blocks 3 & 5. <u>END</u>						
Limited Life parts must be accompanied by maintenance history including total time/total cycles/time since new.						
14. <input type="checkbox"/> New <input type="checkbox"/> Newly Overhauled Certifies that the new or newly overhauled part(s) identified above, except as otherwise specified in block 13, was/were manufactured in accordance with FAA approved design data and airworthiness regulations. NOTE: In case of parts to be exported, any special requirements of the importing country have been met.			19. Return to Service in Accordance with FAR 43.9 Certifies that the work specified in block 13 (or attached) above was carried out in accordance with FAA Airworthiness Regulations and in respect to the work performed the part(s) is (are) approved for return to service.			
15. Signature:		16. FAA Authorization No.	20. Authorized Signature: 		21. Certificate Number: B2PR308J	
17. Name (Typed or Printed):		18. Date:	22. Name (Typed or Printed): William GARNER		23. Date: 9-11-98	

FAA Form 8130-3 (3-96)

* Optional installer must check eligibility with applicable technical data.

DISASSEMBLY NOTES

CORNER BOLT LENGTH: 2.5

LOW STOP NUT TYPE: 1

Mech. Cert. # or Repair Station #

B2PR308J
JAA Authorized

Item 7a

BANYAN PROPELLER SERVICE

FAA REPAIR STATION B2PR308J

DETAILED INSPECTION REPORT

RECEIVING INFORMATION

WOP# 72177 ACCT# 5155 PO# _____ DATE RECEIVED 9-4-98 DATE DUE _____
 CUSTOMER: B.P.S. resale
 AIRCRAFT: Cessna 310 ENGINE: _____ REG # _____
 PROP MANUFACTURER: McCaulley MODEL# 3AF32C87-101 BLADE MODEL# 3 BANC-5.5
 SERIAL # 788984 LOG BOOK: _____ TTSN: _____
 PROPELLER IN FOR: OVERHAUL OTHER(EXPLAIN): Build up to 501R

BLADE S/N OFF:

1) N/A
 2) _____
 3) _____
 4) _____
 5) _____
 6) _____

BLADE S/N ON:

1) F4744445
 2) F4803345
 3) F4813445
 4) N/A
 5) /
 6) _____

CLAMP S/N OFF:

1) _____
 2) _____
 3) _____
 4) _____
 5) _____
 6) _____

CLAMP S/N ON:

1) _____
 2) _____
 3) _____
 4) _____
 5) _____
 6) _____

DISASSEMBLY NOTES

CORNER BOLT LENGTH: 1/4"LOW STOP NUT TYPE: /

PROPELLER & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Total Time
in Service

Description

Make: McCawley

Model: 3AF32C87-NIR/582NC-5.5

Serial No.: 788984

W.O.# 72177

Log Book Entry

~~Turn~~/Hobbs Reading: 1206.9

Date: 8-11-98

Reg. No.: 8422F LH

Overhauled Propeller per McCawley manuals 710930
and 830415. A. P. notes checked through
bi-weekly issue 98-18. - Encl -



1575 W. Commercial Blvd. #31
Fort Lauderdale, FL 33309
(954) 491-3170 • Fax: (954) 491-2006

[Signature]
Authorized Signature

B2PR308J
JAA Authorized

Mech. Cert. # or Repair Station #

RIGHT 8422F

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Date 04-22 19 99	Total Time in Service 1-1555 1206.9	Description Installed overhauled propeller on RIGHT side of C402-0270, N 8422F. Test for satisfactory.
Next Inspection Due:	Time Since Overhaul 0	Mech. Cert. # or Repair Station # <u>Scott Cough 309541311 FA</u>

Date 19 9-25-00	Total Time in Service 1235 Hrs 29.5 MoH	Description 100 Hrs INSP C/W, OK FOR RTS. DPHATT 1752579 AEP
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #

Date 19	Total Time in Service	Description
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #