Volume #: \_\_\_\_\_

## PROPELLER DETAILS

1. Manufacturer _	HARTZEL	L PROPELLE	ER
2. Type/Model/Seri	ies HC-C2Y	F-2CUF	
3. Serial Number	JQ 1638		
4. Date of Manufac	cture		
5. Pitch lock settin	gs		
Date		_/_/	
a) High			
b) Low			
c) Reverse			

Date Tin	ime since new	Time since overhaul	Details of task		Signature	AME ACA/AMO SCA/AMO
April 16/10	0	0	New Propeller received on wo# 4509. BATCH # 10-060	PROPWORKSP	ROPELLER SYSTE	MS INC.
			4509 WO BATCH # 10-060		Children and the second	
			The state of the s	A.M.O. # 105-99	(WINNIPEG, MAN	A P a
				and the second s		A.P.O
				279019		STAMP
				MICHAELHUD	EC	STAIVIT
1 10 7016						
	0	0	Installed prop on Cersna 310d SIN	39279 N6979 T. Installed 1/A/W		
Aircrof+ Hol	bbs	3095	Hartzell prop manual 115N, Props STA	by Hatrell STC # SA00799ch. Run up ups good.		
			1.42 516	Tame Sot AP 28772401A		
7-1-2011			I certify that this prop has been	Inspected IAIN an annual Inspection		
Tach 3186.7	7		and was determined to be in	airworthy condition turn son		DE SE
TSN 91,2			and was determined to be in	AP Z677 Z40 ; M		
1310 11,6				11 281124011		
9 12 - 1						
9-13-2012			and was determined to be in	airworthy condition.	0-7	
ach 3298			and was determined to be in	airworthy condition,		
TJN 203			Lann Sor AP 28772401A			
		DEVI	LS LAKE AERO SERVICE 701-662-4416			
		40/4/	2012 Tach 3420 TTSN 325 N6979T	3-20-2019 Tach 3604.4		
			La Desped Prop. I certify that this prop has			
			inspected IAW an annual inspection and was rmined to be in airworthy Condition.	Inspeche prop. found to be	'n safe	
		deter	ner Sotvik A&P 2877240 to So	condition for Intended Form	Hight	
		Tani	Tel Solvik Adi Zotta - W /Jos	from OUL to KOEB at this	rime.	
				1 10m 100 100		
				AP7 877 24		
			STAKE AERO SERVICE 701-662-4416	77768772	0/1	
		DEVIL	S LAKE AERO SERVICE 701-662-4416 014 Hobbs 3487.9 TTSN 392.9 N6979T			
			Prosped Prop. I certify that this prop has			
		hoon in	penected IAW an annual inspection and was			
		determ	ined to be in airworthy Condition.			
		Tanner	Sotvik A&P 2877240 & S			
					THE RESERVE	
					TO THE PARTY OF TH	
	To the same	The second				

Date//	Time since new	Time since overhaul	Details of task		Signature	AME ACA/AMO SCA/AMO
1-5-2016	Tach	3543.3	Replaced Low Pitch Stop PIN AZYON	for up Adj as per SM. Inspected & prop has been inspected IAW an to be in airwoithy condition.	Tan Sor	AP2877740
	TTSN	448.3	Oressel I certify that this	and has been inspected IAW an		
		444	annual inspection and was E. I	1 he in armoithu condition.		
			Toons			
		THE RESIDENCE				
			CAN CASE TO SEE STEEL SEE			
			N. 113 (1823) A			
		-1113	Manager College Colleg			
			A CONTRACT OF STREET			
	5	14/13/2	7677			
	-	117 125	Maried the arranged to			
			air worthy and the			
			•			
-		-				
			AND A AND SET OF			
		144 113			2 1 2 2 2 2 2 2	A DE PROPERTO
						Page

Volume #: \_\_\_\_\_

## PROPELLER DETAILS

1.	Manufacturer	HA	RTZELL	PROP	EUE	~				
2.	Type/Model/Series _	H	1C- C241	2c	UF					
3.	Serial Number	J	2 164B							
4.	Date of Manufacture	_								11.
5.	Pitch lock settings									
	Date —	_/_	_/	/_	_/_	-	-	_/	_/	-
	a) High					_	_	-	-	-
	b) Low					-	-		-	
	c) Reverse					_	-	-		-//

Date/	Time since new	Time since overhaul	Details of task		Signature	AME ACA/AMO SCA/AMO
APRIL 16, 2010	0	0	New propeller Received on WO# 4508. BATCH# 10-060	PROPWOR	KS PROPELLER S	YSTEMS INC.
			WO# 4508 . BATCH# 10-060	AMO #1	05-99 (WINNIPEG,	MANITORA)
			77. (61/7 (0-06)	A.W.V.		6
				The same of the sa		4
				MICHALI	HUDEC	STAM
-19-2010	0	0		111 070 T 111 6-11 121 11 1 110111		
ach 3095		0	installed prop on Cessna 310d 5/N39779	N6979T LH Engine, Installed ITAIN by Hartiell STC # SA007990h. Run up apsign	1	
ach 3093			Hartzell prop Manual 115N Prop STC'S	Tames Son AP 28172401A	000	
1 1 2 11						
7-1-2011	2		and was determined to be in	Inspected IAW an annual impertion		
Tach 3186. TSN 91.			Tanno Sop AP2877240/A	air wo thy condition.		
3 V (1.	_		17 20112401A			
7-13-12			1 certify that this pop was	Inspected IAW an annual inspect	tion	
414 329	8		and was determined to be in	arrworthy condition.		
TSN 703			Janus 800 AP 28772401A			
	DEV	/ILS LAKE AER	O SERVICE 701-662-4416	3-20-2019 Tach 3604.	7	
		4/2013 Tach 342	Drop I certify that this prop has			
				Inspected Price Found prop	to be	
	— dete	ermined to be in	airworthy Condition	in sets maditure the inter	de 2	
	Tan	nner Sotvik A&F	2877240	in sate condition for intest formy Night from DVL to	HOEB,	
				T Sor		
	DE	VILS LAKE AEI	RO SERVICE 701-662-4416	AP 2877 240	M	
			3487.9 TTSN 392.9 N6979T			A diversity
	be	en inspected IAV	ed Prop. I certify that this prop has  N an annual inspection and was			
		nner Sotvik A&	P 2877240			
			The state of the s			

TTSN Y48.3 on annual injection and was been a servent type condition.  The servent type condition and the servent type condition and the servent type condition.							
	Date/		overhaul				A STATE OF THE PARTY OF THE PAR
	1-5-2016	Tach	3543.3	Jospacial , Promil I contil I	this amo has been inspected IAM	Tempto	AP 2877240
			448.3	inspected of vierted, I terfily that	this from the in alreal the condition		
			1100	ari annual inspection and was	forme to the man war the	1	
			A CONTRACTOR OF THE PARTY OF TH				
			- N. W. S.				
				and the same of the Landson			
				Marce of Mr as made			
				A STATE OF THE STA			
				1413			
							THE PERSON NAMED IN
							-
							Pa