FAA Form ACA-337 by Date,	airs and Major Alterations To or to the Work Order by Number and the Approving Agency
N: 727AV  Details of this inspection are  Date: 6-27-19  Make/Model: 16 ms  Make/Model: 1 certify the ATC trans  required by FAR 91.4  and found to comply	on file at this facility under:

**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of TOTAL **TODAYS** RECORDING DATE TIME IN Technician or Repair Facility. (See back pages for other specific entries.) FLIGHT TACH SERVICE TIME ELITE AIR SERVICE 143 E CHICAGO RD COLDWATER MI 49036 PH: 517 278-6516 S/N 42-121892 **TSMO: 177** Hobbs: 151.9 10/012015 R-985 Performed Annual inspection per FAR 43 apx D and 91.409(a)(1) Researched AD's and all AD notes complied with at this time. Inspected all hoses and lines no defects noted at this time. Performed compression check as follows #1 72/80, #2 75/80, #3 79/80, #4 76/80, #5 74/80, #6 76/80, #7 79/80, #8 78/80, #9 79/80.

Performed run-up and ops checked all satisfactory at this time. Hillard D. Hiner Jr. AP\$135719IA I certify that this Engine has been inspected in accordance with an Annual Inspection and determined to be in Airworthy condition at this time. Hillard D. Hiner Jr.AP3105719IA 91 ASA

RECORDING TACH TIME

TODAYS FLIGHT TOTAL TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)




Elite Air Service 300 Airport Dr. Coldwater MI 49036 517 278-6516

1st 2016, N727AV Beechcraft G18S S#BA560, P&W R985-AN14B S#42-121892, Hobbs: 161.2, TT 4700 SMOH 181

regine as required by FAR91.409(a)(1) per checklist meeting requirements of FAR 43.15(c)(1) and FAR 43 appendix D. 1/77 2/79 3/79 4/78 5/79 6/76 7/79 8/79 9/79.

IAW Beechcraft G18S and P&W R985 maintaince documents. Preformed post inspection operational check per FAR43.15(c)(2). as inspected in accordance with an annual inspection and has been determined to be in airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA



ELITE AIR SERVICE 143 E CHICAGO RD COLDWATER MI 49036

FAX 517 279-2363

PH: 517 278-6516

07/07/2017 N727AV

Beechcraft G18S

S/N: BA-560

Hobbs: 0197.5

Engine: R985-14B

Performed oil change on Left engine; drained oil, removed oil filter and Inspected filter for contaminants; installed new oil filter P/N 122R, and serviced engine with 25W60XC oil. ALL work performed using G18S maintenance documents. Performed a run-up ops and leak check; no defects noted at this time.

Walter H Paegel IV AP3737207

) 1991 ASA

All work done IAW Beechcraft G18S and P&W R985 maintenance documents. Completed post inspection operational check per FAR43.15(c)(2). This engine was inspected in accordance with an annual/100 inspection and has been

determined to be in an airworthy condition at this time.

Rueben A Walkup A&P 3368961 IA

11

#! Ti

50 ha

Joe

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alter Entries must be endorsed with Name, Rating and Certificate Num Technician or Repair Facility. (See back pages for other specific e
			10	
05/20/20	E L 1	TE	AI	RSERVICE
lnsnecte	d Engine IAV	V FAR 43	& Whitney I	R-985-14B ser# 42-121892 SMOH: 253.7 HOBBS: 285.9 O' check list and Pratt & Whitney Maintenance Manual.
Cylinder	Compressio	n #1-78/8	0. #2-78/80	, #3-75/80, #4-79/80, #5-79/80, #6-78/80, #7-79/80, #8-78/80,
#9-78/80	0. Oil Filter c	hange che	ecked old on	e clear of metal. Timing checked @ 25 degrees BTDC with
Time-Rit	te Both Mag	s. Cleaned	gapped and	I tested all front and rear spark plugs. Washed engine with
solvent,	cleaned cov	vI. All AD's	through 5/3	30/19 complied with and listed. I certify that this nower plant
			A -111 /	and ws determined to be un an airworthy condition.
Joel E. N	Newton 5743	06216 A 8	&P Journ	