

Date: 06/01/2021	Make/Model: Textron (Cessna) 180	Tail #: N9206C	Serial #: 180-31305
Airframe Hours: TTAF: 3226.54 TACH: 379.54			
Misc:			
Engine: Continental O-470-J	Serial #: 46769-9-J-R	Hours: TTE: 1507.47 SMOH: 148.47 STOH: 2.77	
Propeller: McCauley 2A36C18	Serial #: 54322	Hours: SMOH: 138.47	

Textron (Cessna) 180

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
59-10-03 07/15/59 Airframe	Position Light Flasher Switch	12/15/2020 TTAF: 3226.54	DNA by not being installed		no further action required	<i>B. Klenoski</i> 3211171 A & P
68-17-04 09/07/68 Airframe	Stall Warning System	12/15/2020 TTAF: 3226.54	DNA by serial number	Yes*	no action required	<i>B. Klenoski</i> 3211171 A & P
73-17-01 08/16/73 Airframe	Fuel Transfer Pump Operation	12/15/2020 TTAF: 3226.54	DNA not installed		no action required	<i>B. Klenoski</i> 3211171 A & P
73-23-07 11/19/73 Airframe	Spar Attachment Fitting	12/15/2020 TTAF: 3226.54	DNA by serial number		no action required	<i>B. Klenoski</i> 3211171 A & P
75-16-01 07/30/75 Airframe	Fuel System Placards	12/15/2020 TTAF: 3226.54	PCW placards		no action required	<i>B. Klenoski</i> 3211171 A & P
77-04-05 03/01/77 Airframe	Carburetor Air Intake	12/15/2020 TTAF: 3226.54	DNA by serial number		no action required	<i>B. Klenoski</i> 3211171 A & P
79-08-03 05/21/79 Airframe	Electrical System	12/15/2020 TTAF: 3226.54	PCW cigar lighter protected by breaker on new installation		no further action required	<i>B. Klenoski</i> 3211171 A & P
79-10-14 R1 05/30/88 Airframe	Fuel Tank Venting	12/15/2020 TTAF: 3226.54	Complied with by installation of under wing fuel tank vent KIT SK182-85		no further action required	<i>B. Klenoski</i> 3211171 A & P
79-25-07 12/13/79 Airframe	Alternator Ground	12/15/2020 TTAF: 3226.54	DNA by serial number but installed a ground wire because alternator installed.		no further action required	<i>B. Klenoski</i> 3211171 A & P
83-17-06 09/01/83 Airframe	Aileron Balance Weights	12/15/2020 TTAF: 3226.54	DNA Robertson kit not installed		no action required	<i>B. Klenoski</i> 3211171 A & P
84-10-01 R1 07/05/88 Airframe	Quick Drains For Water In Fuel	12/15/2020 TTAF: 3226.54	SE84-9 Rev 2 Installed new bladders and drains	Yes	no further action required	<i>B. Klenoski</i> 3211171 A & P
90-21-08 11/13/90 Airframe	Fuel Tank Bladder Vent Tube	12/15/2020 TTAF: 3226.54	Installed SK 180-6 under wing vent		no further action required	<i>B. Klenoski</i> 3211171 A & P
97-01-13 02/03/97 Airframe	Collapsed Fuel, Oil, Hydraulic Hoses	12/15/2020 TTAF: 3226.54	New hoses installed		no further action required	<i>B. Klenoski</i> 3211171 A & P
98-16-04 09/21/98 Airframe	Angle Stiffener On Wing	12/15/2020 TTAF: 3226.54	DNA extensions not installed		no action required	<i>B. Klenoski</i> 3211171 A & P

98-23-02 12/22/98 Airframe	Wheel Skis	12/15/2020 TTAF: 3226.54	DNA not installed		no action required	<i>B. Klawnski</i> 3211171 A & P
04-19-01 11/01/04 Airframe	Pilot and Co-Pilot Shoulder Harness	12/15/2020 TTAF: 3226.54	DNA accessory kit not installed		no action required	<i>B. Klawnski</i> 3211171 A & P
08-10-02 05/12/08 Airframe	Alternate Static Air Source Selector Valve	12/15/2020 TTAF: 3226.54	DNA not installed		no action required	<i>B. Klawnski</i> 3211171 A & P
08-26-10 01/05/09 Airframe	Alternate Static Air Source Selector Valve	12/15/2020 TTAF: 3226.54	DNA not installed		no action required	<i>B. Klawnski</i> 3211171 A & P
11-10-09 06/17/11 Airframe	Seat Rail/Track Assembly	06/01/2021 TTAF: 3226.54	Seat lock system checked by measurement and visual inspection	Yes	06/22 or TTAF: 3326.54	<i>B. Klawnski</i> 3211171 A & P
20-21-22 12/07/20 Airframe	Tailcone and Horizontal Stabilizer Attachment Structure	06/01/2021 TTAF: 3226.54	SEL-55-01 500 hrs TIS or 5yrs whichever occurs first Visual inspection	Yes	06/2026 or TTAF: 3726.54	<i>B. Klawnski</i> 3211171 A & P

Engine: Continental O-470-J

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
56-06-01 07/01/56 Engine	Piston Pin Assembly Replacement	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
63-15-01 07/25/63 Engine	Exhaust Valve Replacement	06/14/66 TTE:1864.3	PCW at overhaul		no action required	<i>B. Klawnski</i> 3211171 A & P
73-13-04 06/20/73 Engine	Carburetor Bowl Drain Plug	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
79-05-09 03/12/79 Engine	Oil Pressure Relief Valve Housing	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
88-03-06 04/15/88 Engine	Oil Filter	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA TCM filter part number not used		do not se filter P/N 649309 or 649310	<i>B. Klawnski</i> 3211171 A & P
91-19-03 09/29/91 Engine	Collapsed Oil Filter Elements	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA DATE CODE Filters not used		Check date codes AD91- 9-03 (b)	<i>B. Klawnski</i> 3211171 A & P
93-10-02 08/12/93 Engine	Missing Cylinder Valve Retainer Key	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA by date of purchase		no action required	<i>B. Klawnski</i> 3211171 A & P
97-21-02 10/27/97 Engine	Side Loading Of Pistons	12/15/2020 TTAF: 3226.54 SMOH: 148.47	CSB97-10A DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
98-17-11 10/19/98 Engine	Crankshafts Installed by Nelson Balancing Service	12/15/2020 TTAF: 3226.54 SMOH: 148.47	DNA not listed in AD		no action required	<i>B. Klawnski</i> 3211171 A & P
99-19-01 09/30/99 Engine	Crankshaft Cheek Cracks	12/15/2020 TTAF: 3226.54 SMOH: 148.47	MSB 9903C DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
00-23-21 12/12/00 Engine	Crankshaft Connecting Rod Journal Failure	12/15/2020 TTAF: 3226.54 SMOH: 148.47	MSB 00-5C DNA by date of manufacture		no action required	<i>B. Klawnski</i> 3211171 A & P

10-11-04 06/16/10 Engine	Hydraulic Lifter Face Wear	06/14/66 TTE:1864.3	MSB09-8A DNA by lifter part number		no action required	<i>B. Klawnski</i> 3211171 A & P
--------------------------------	----------------------------	---------------------	------------------------------------	--	--------------------	-------------------------------------

Propeller: McCauley 2A36C18

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
64-24-04 11/20/64 Propeller	Blade Threaded Shank Cracks	11/24/82 SMOH: 0.0	SB 48-C complied with		no action required	<i>B. Klawnski</i> 3211171 A & P
77-16-01 08/09/77 Propeller	Blade Actuating Pin Failures	11/24/82 SMOH: 0.0	DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
05-14-11 08/17/05 Propeller	Southern California Propeller Serviced Propellers		Service not used		no action required	<i>B. Klawnski</i> 3211171 A & P

Appliance: Power Plant - Magnetos

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
94-01-03 R2 06/28/95 Appliance	S-20, S-200, S-600, S-1200 Series - Magneto Failure	12/15/2020 TTAF: 3226.54 SMOH: 148.47	MSB644 DNA by serial number		no action required	<i>B. Klawnski</i> 3211171 A & P
94-06-09 05/20/94 Appliance	SC-20, SC-200, S-1200 Series & Capacitors 10-349276 - Non-Grounded Magneto	12/15/2020 TTAF: 3226.54 SMOH: 148.47	PCW at overhaul		no further action required	<i>B. Klawnski</i> 3211171 A & P
05-12-06 07/19/05 Appliance	S-20, S-1200, D-2000, D-3000 Series - Impulse Coupling Assembly	12/15/2020 TTAF: 3226.54 SMOH: 148.47	Left & Right Mags new Snap ring couplings installed	Yes*	TTAF: 3726.54 SMOH: 648.47	<i>B. Klawnski</i> 3211171 A & P